


Spike Connector Kit - Install Instructions

In the Box




Spike Connectors (8)

Depending what placement you want: at the **Head end** or at the **Shade end**

1. Connect the RJ 45 to the UTP cable (Janus side) and
2. Connect the Terminal Block to Multi connector cable (shade side)

at Head end



at Shade end

